

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION III 1650 Arch Street

Philadelphia, Pennsylvania 19103-2029

In Reply Refer to: 3AP20

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

DEC 2 7 2017

Jon T. Hickman EHS Specialist Ascent Resources 1000 Utica Way Cambridge OH 43725

Dear Mr. Hickman:

Enclosed is the Air Compliance Inspection Report for the United States Environmental Protection Agency's (EPA) September 18, 2017 inspection of Ascent Resources' (Ascent) facilities located in Wetzel County, West Virginia. Please take note of the Areas of Concern on page 8 of the enclosed report. After you and your staff have reviewed the report, EPA would like to provide Ascent the opportunity to discuss the Areas of Concern identified and Ascent's potential remedies. Specifically, EPA is interested in discussing the design and operation of the storage tank vapor capture systems and controls at Ascent facilities. In addition to the inspection report, a compliance alert issued to industry by EPA in September 2015 is included that addresses some general compliance concerns regarding emissions from storage vessels at oil and natural gas production facilities.

If you have questions or comments, or would like to schedule a meeting, please contact Natalia Vazquez of the Air Protection Division or Mr. Doug Snyder of the Office of Regional Counsel at (215) 814-2692 within fifteen (15) days of receiving the inspection report.

Sincerely,

Zelma Maldonado, Associate Director Office of Air Enforcement & Compliance Assistance

Enclosure

ce: Christopher Williams and Daniel Hoyt, USEPA Air Enforcement Division, Washington, D.C.

105 A 5 1.30



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION III

1650 Arch Street

Philadelphia, Pennsylvania 19103-2029

Inspection Date(s):

09/18/2017

Regulatory

Program(s):

SIP. NSPS

Company name:

Ascent Resources

Facility Physical

Location:

Wileyville, West Virginia

Mailing Address:

1000 Utica Way

Cambridge Ohio 43725

County/Parish:

Wetzel County

Facility Contact:

Jon T. Hickman, EHS Specialist

jon.hickman@ascentresources.com, 740-432-9002

AFS Number:

5410300051, Hoyt 401

5410300047 Hoyt 402 5410300067 Hoyt 403 5410300080 Long 408/409 5410300104 Mary Miller 5410300098 WJ Criswell 405

NAICS:

211113 - Conventional Oil and Gas Extraction

SIC:

1311: Crude Petroleum and Natural Gas

Attendees:

Facility Representatives:

Jon T Hickman, EH&S, 740-432-9002

Amanda Warnock, EH&S (Environment)

Casey Pingley, EH&S (Safety)

EM Maykowski, Optical Gas Imaging Camera Technician

Brent Vanderhoff, Production

EPA Inspectors:

Daniel Hoyt, USEPA Headquarter/2248, 202-564-7898 Natalia Vazquez, USEPA Region III/3AP20, 215-814-2121 Steve Rieck, USEPA Region IV/9T25, 404-562-9177 Page 2 of 8

Ascent Resources Inspection Date(s): 09/18/2017

EPA Lead Inspector

Telus 12/13/2

italia Vazquez D:

EPA Inspector

aniel Hoyt Date

Supervisor

Zelma Maldonado Date

I. Introduction

The United States Environmental Protection Agency (EPA) visited several Ascent Resources (Ascent) wellpads to verify compliance with permitting requirements and applicable State and Federal regulations. On September 12, 2017, the EPA notified Evan Pearson of Ascent by phone and email of the Clean Air Act (CAA) inspection to be conducted on September 18, 2017. At a later email (9/14/2017), Ascent notified EPA that Jon Hickman would be the point of contact (see Attachment #1).

A. Summary of the Facility-

EPA visited seven (7) wellpads owned, drilled and operated by Ascent. The names of the seven visited sites are: Long 408 and 409, Hoyt 403, Hoyt 402, Hoyt 401, Hoyt 404, WJ Criswell 405, Mary Miller GRT WZ. The wells are subject to 40 C.F.R. Part 60 Subpart OOOO – Standards of Performance for Crude Oil and Natural Gas Production, Transmission and Distribution for which Construction, Modification or Reconstruction Commenced After August 23, 2011 and on or before September 18, 2015 (NSPS OOOO) and 40 CFR Part 60 Subpart OOOOa – Standard of Performance for Crude Oil and Natural Gas Facilities for which Construction, Modification or Reconstruction Commenced After September 18, 2015 (NSPS OOOOa)¹.

B. Inspection Opening Conference-

EPA met with Ascent representatives at a gas station in New Martinsville, West Virginia (39.6421 N, 80.8583 W), at 9am on September 18, 2017. Daniel Hoyt (Headquarters), Natalia Vazquez (Region III) and Stephen Rieck (Region IV) were representing EPA. The EPA inspection team presented their credentials. The West Virginia Department of Environmental Protection was invited to attend; however, they were not able to participate in the inspection. EPA informed Ascent that the purpose of the inspection was to assess compliance with the applicable regulations at the wellpads. EPA informed Ascent it would be taking photographs and videos with a digital camera and an optical gas imagining (OGI) camera, respectively. Ascent was informed that it is their right to claim any photo, video and document as Confidential Business Information (CBI) and EPA would treat it as such. Ascent did not claim any material as CBI during the inspection. Ascent provided a short safety orientation to the EPA inspection team.

¹ Ascent confirmed this by email on December 5, 2017.

II. Process Overview

Each of the seven sites visited by EPA had several horizontally drilled wells that extract natural gas and condensates. Each site was equipped with sand traps, gas processing units (GPU), condensate storage tanks, produced water storage tanks, in addition to the wells. The sand traps filter out solid material that flows out of the well with the natural gas to prevent it from entering the GPU. The GPU's are 3-phase separators, which separate the gas stream into natural gas, condensate liquids and produced water. Storage tanks are manifolded together through a closed vent system that collects tank vapors and routes them to a combustion control device.

All seven sites are considered minor sources for the purposes of permitting. Each site has either a minor source permit or a general permit G70 for natural gas production facilities (both under 45CSR13). At the end of the day on September 18, Mr. Hickman provided EPA with copies of the permits for all sites, except WJ Criswell 405². The permits are listed below.

Facility name	Permit type and number	Dates
Hoyt 401	Minor R13-2992C	January 13, 2017
Hoyt 402	Minor R13-2966C	January 30, 2017
Hoyt 403	Minor R13-3091A	March 21, 2017
Hoyt 404 ³	Minor R13-2985C	January 6, 2017
Long 408 and 409	Class II General Permit	September 30,
<u> </u>	G70-C	2016
Mary Miller GRT WZ	Minor R13-3349A	June 16, 2017

The general permit G70-C establishes the following maximum annual emission limits:

Pollutant	Maximum Annual Emission Limit (tpy)
Nitrogen oxides (NO _x)	50
Carbon monoxide (CO)	80
Volatile organic compounds (VOC)	80
Particulate matter (PM)	20
Sulfur Dioxide (SO ₂)	20
Any single Hazardous air pollutant (HAP)	8
Total Hazardous air pollutant (HAPs)	20

² Ascent provided WJ Criswell by email on October 12, 2017.

³ Hoyt 404 also has the name John Rush 404, which was confirmed with Latitude and Longitude provided in the permit.

AFS-5410300051, 5410300047, 5410300067, 5410300080, 5410300104, 5410300098

III. Plant Tour/Walkthrough

EPA visited seven well pads owned by Ascent Resources. During each visit, EPA used the optical gas imaging (OGI) camera and photoionization detector (PID) to identify emissions. PID readings of the leak observed at sites visited can be found in Attachment #2, in the videos and photographs log.

Long 408 and 409 39.5975N, 80.6747W

EPA arrived at the Long well site at 9:48am on September 18, 2017. The site has 11 wells and the last flowback was completed sometime between December 2014 and January 2015. There is a sand trap and a GPU dedicated to each well. The GPUs were originally 3-phase separators; but now are 2-phase, in that they are set to only remove liquids from the gas stream. Mr. Vanderhoff stated that the liquids removed from the gas stream are sent to the heater treater to separate condensate and produced water. The material streams from the heater treater are then sent to the corresponding storage tank. There are 14 storage tanks, 8 for condensate and 6 for produced water. The 14 tanks are divided into 3 groups and in each group, the tanks are manifolded together and share a common pressure relief valve. The closed vent systems for each of the three storage tank groups route vapor to a shared enclosed combustor. The natural gas separated at the GPU is sent to Blue Racer Midstream via an underground pipeline. Mr. Vanderhoff stated that the midstream company maintains a pressure in mainline around 300 psi. This facility produced 20624.25 MCF of natural gas on the day prior to the inspection. This facility also has a stabilizer and a pressurized natural gas liquids tank, however, both pieces of equipment were out of service during the inspection. Mr. Vanderhoff explained that Ascent's actual liquid production did not meet anticipated production.

EPA conducted a walkthrough of the site, Mr. Hoyt used an OGI camera (brand: FLIR) to identify emissions and Mr. Rieck used a photoionization detector (PID) to measure the concentration of VOCs emitted. Emissions were observed and confirmed emanating from the following equipment:

- 1. GPU unit 409S-5H,
- 2. enclosed combustor (this was not confirmed with the PID),
- 3. pressure relief valve on top of condensate tank with AST number 052-00000338,
- 4. thief hatch on condensate tank with AST number 052-00001029,
- 5. thief hatch on condensate tank with AST number 052-00000311,
- 6. thief hatch on condensate tank with AST number 052-00000322,
- 7. thief hatch on condensate tank with AST number 052-00000350,
- thief hatch on condensate tank with AST number 052-00000328,
- thief hatch on produced water tank with AST number 052-00001031,
- 10. thief hatch on condensate tank with AST number 052-00001027 (odor detected by Ms. Vazquez),
- $11.\,\,\,\,\,\,$ pressure relief valve on top of condensate tank with AST number 052-00001027,
- 12. thief hatch on produced water tank with AST number 052-00000298,
- 13. thief hatch on produced water tank with AST number 052-00000345, and
- 14. thief hatch in produced water tank with AST number 052-00000333.

Hoyt 403 39.5992N, 80.6539W

EPA arrived at the Hoyt 403 well site at 11:53am on September 18, 2017. There are 6 wells at this site. This facility had a natural gas flowrate of 9132.72 MCF on 9/17/2017. This site has two gun barrels, each one connected to two condensate tanks and two produced water tanks. Gun barrel is a condensate/produced water separator. Both gun barrels have stains on their surfaces. This facility has a vapor recovery unit (VRU) that was out of service during the inspection. Mr. Vanderhoff said that Ascent does not label equipment that is out of service, he knows which equipment is not being used by memory. While observing the storage tanks, Mr. Hoyt noticed an indentation and standing water on the produced water storage tank #2-south. Emissions were observed and confirmed, during the site walk through, coming from the following equipment:

- 1. GPU 1H,
- 2. diaphragm in GPU 1H, and
- 3. thief hatch in produced water tank with AST number 052-00000347.

Hoyt 402 39.5986N, 80.6519W

EPA arrived at the Hoyt 403 well site at 12:35pm on September 18, 2017. The site has 6 wells and produced 3878 MCF of natural gas the previous day. The site has an enclosed combustor, 2 gun barrels, 4 condensate tanks and 4 produced water tanks. During the walkthrough, EPA detected odors coming from several pieces of equipment as indicated below. EPA noticed stains

on the gun barrel tank and on a storage tank (see photo DSC00802). Emissions were observed and confirmed emanating from the following equipment:

- 1. GPU 5H (odor detected by Ms. Vazquez),
- 2. thief hatch in condensate tank with AST number 052-00000312,
- 3. thief hatch in condensate tank with AST number 052-00000320,
- 4. thief hatch in produced water tank with AST number 052-00000332,
- 5. thief hatch in produced water tank with AST number 052-00000312,
- 6. thief hatch in condensate tank with AST number 052-00000339 (odor detected by Mr. Hoyt),
- 7. thief hatch in produced water tank with AST number 052-00000314 (odor detected by Mr. Hoyt and Ms. Vazquez), and
- 8. thief hatch in produced water tank with AST number 052-00000324 (odor detected by Mr. Hoyt and Ms. Vazquez).

Hoyt 401 39.5975N, 80.6522W

EPA arrived at Hoyt 401 wellsite at 1:56pm on September 18, 2017. The site has 6 wells and produced 7228 MCF of natural gas the previous day. The site has 6 line heaters, 2 gun barrels, 4 condensate tanks and 4 produced water tanks. Stains were observed at the two gun barrels. The site has a candle-stick flare to control emissions from the storage tanks. EPA did not observe any emissions with the OGI camera.

Hoyt 404 39.6111N, 80.6378W

EPA arrived at the site at 2:29 pm on September 18, 2017. The site has 6 wells and is producing approximately 1 bbl of liquids per day according to Mr. Vanderhoff. The site had a gas flow of 7423 MCF the day prior to the inspection. The site has 6 sand traps, 6 line heaters, 2 gun barrels, 4 condensate tanks and 4 produced water tanks. Mr. Vanderhoff mentioned that the last flowback was around spring of 2013. The site has a flare that was shutdown. EPA did not observe any emissions with the OGI camera.

WJ Criswell 405 39.6086N, 80.6181W

EPA arrived at the site at 2:54pm on September 18, 2017. The facility currently has 3 wells. The facility had a gas flow of 12663 MCF on the previous day. The site has 3 sand traps, 3 GPU, 3 condensate tanks, 3 produced water tanks. The site also has a NGL tank that was out of service. The facility has an enclosed combustor that appeared to not be operating during the inspection. The tank header piping appeared to be connected to the combustor. EPA observed and confirmed emissions emanating from two locations:

- thief hatch in produced water tank with AST number 052-00001147 and
- 2. thief hatch in produced water tank with AST number 052-00001144.

Mary Miller GRT WZ 39.6156N, 80.6144W

EPA arrived at the site at 3:19pm on September 18, 2017. The well pad consisted of 4 wells. The site produced 19006 MCF of natural gas during the previous day. This facility has a glycol heater that was not operating during the inspection. Mr. Vanderhoff explained that it was installed to prevent freezing in the pipeline, but Ascent has never encountered a problem with

AFS-5410300051, 5410300047, 5410300067, 5410300080, 5410300104, 5410300098

freezing. The site has 4 sand traps, 4 GPUs, 2 condensate tanks, and 2 produced water tanks. The site has a candle stick flare to control emissions from the condensate tanks. Excess emissions were not observed with the OGI camera. At the end of the facility walk through, Ascent and EPA scheduled a close out meeting for 9/21/2017 at 2:30 pm.

IV. Records Review

EPA did not request and did not complete a records review during the inspection. Ascent's closest office is located in Parkersburg, West Virginia; approximately an hour away from the sites. During the inspection, EPA received the permits from all sites, except WJ Criswell 405, which was provided by email in October 12, 2017. EPA requested several documents during the closing meeting on September 21, 2017. A list with the requested documents was also sent by email to Ascent on September 28, 2017 (see Attachment #3). Ascent provided all requested documents by email on October 12, 2017.

V. Closing Conference

The closeout meeting took place at 2:30pm on September 21, 2017 at the Western Sizzlin located on 37 Neal Run Blvd, Parkersburg, WV. Mr. Hoyt, Ms. Vazquez, Mr. Hickman and Ms. Warnock were present at the meeting, in addition to Mr. Bob Adams, Ascent's Operations EH&S Field Manager. EPA shared a CD containing all videos and photographs taken during the inspection with Ascent.

EPA and Ascent discussed the company's monitoring, a well-pad operator's responsibilities, and SOP. Ascent indicated that an operator visits each site daily to walk around, verify alarms and shutdown events. If necessary, the operator takes the necessary steps to prevent continuous emission releases. Ascent conducts leak detection and repair (LDAR) with an OGI camera semi-annually and performs auditory, visual and olfactory monitoring on a daily basis. Mr. Maykowski uses an OGI camera, FLIR GF320 model, during the LDAR monitoring. Ascent said it would provide Standard Operating Practices (SOP) related to the LDAR procedure and documents related to best engineering guidance related to thief hatches and pressure relief valves. Ascent provided several documents related to LDAR and maintenance in October 12, 2017.

Ascent informed EPA that the pneumatic controllers at all their facilities are low-bleed pneumatics. EPA asked Ascent to provide schematic and documentation for their pneumatic controllers.

EPA also, requested engineering documents related to the enclosed combustor and documentation of any repairs related to the emissions observed. EPA stated that an inspection report documenting the observations during the onsite inspections would be sent to Ascent.

VI. Areas of Concern

The following have been identified as potential issues identified during the inspection. They are issues that require either further investigation by EPA or additional information and/or explanation by Ascent. Any additional information concerning these areas provided by Ascent would become useful in determining the extent of any future actions by EPA.

- Emissions from the enclosed combustor in Long 408 and 409 well-pad observed with the OGI camera.
- 2. Emissions emitted from thief hatches and pressure relief valves at the following well-pads with the OGI camera. The VOC PID readings for each observed emission with the OGI camera are included in Attachment #2. The emissions observed from the pressure relief valves were not confirmed with the PID due to difficulty to reach.
 - a. Long 408 and 409 from one GPU, two out of the three pressure relief valves, the thief hatches of six condensate tanks and the thief hatches of four produced water tanks
 - b. Hoyt 403 from one GPU and the thief hatch of one produced water tank
 - Hoyt 402 from one GPU, the thief hatches of three condensate tanks and the thief hatches of four produced water tanks
 - d. WJ Criswell 405 from the thief hatches of two produced water tanks

VII. List of Attachments

- 1. Email confirming the CAA inspection, dated 9/12/2017
- 2. Photo and Video Log
- 3. Email with the list of the requested documents at the close-out meeting, dated 9/28/2017

Vazquez, Natalia

From: Hoyt, Daniel

Sent: Tuesday, September 12, 2017 4:23 PM evan.pearson@ascentresources.com

Cc: Vazquez, Natalia

Subject: Ascent Resources: Notification for Site Visits

Hello Evan Pearson,

We spoke earlier today, and I notified you that EPA will be conducting site visits at Ascent Resources facilities in the counties of Wetzel, Doddridge and Tyler in West Virginia during the week of September 18 through September 22, 2017. I will be accompanied by Natalia Vazquez of EPA (cc'd) during the site visits. The exact locations that we will visit have not been determined. We request that an Ascent Resources representative accompany us throughout the week at each of the sites that we visit. You mentioned that Ascent Resources has an office in Parkersburg, WV, where we could meet on the morning of September 18, at 9 am. It looks like that location could work for us. Please reply to all and include the contact information of the person who we will need to coordinate with. Natalia or I will contact the designated individual, to coordinate meeting details for the week.

Thanks,

Dan

Daniel Hoyt, Environmental Engineer
US Environmental Protection Agency
Office of Enforcement and Compliance Assurance
Office of Civil Enforcement - Air Enforcement Division
(202) 564-7898
1200 Pennsylvania Ave, NW
WJC-S, MC 2242A
Washington, DC 20460 (mail) or 20004 (courier)

		Ascent Resources 9/18/2017	
		Facility: Long 408 and 409	
File Number	Time	Description	PID reading
IR_0212		Test photograph, please disregard	
DSC00763	9:52 am	Sign at entrance of Long 408 and 409 wellpad Latitude: 39.5975N	
		Longitude:80.6747W Address: 1220 Ashland Ridge Rd. Wileyville WV 26581 Photograph by Steve Rieck	
DSC00764	9:52 am	Sign for each well at the wellpad. Photograph by Steve Rieck	
DSC00765	10:09 am	Well heads, sand traps and GPUs Photograph by Natalia Vazquez	
DSC00766	10:10 am	Wellhead Long 409 S-6H Photograph by Natalia Vazquez	
MOV_0213	10:14	Test video, please disregard Video by Daniel Hoyt	
DSC00767	10:15 am	Data Output Screen, Gas Meter, Sales Check Meter Photograph by Natalia Vazquez	
MOV_0214	10:16 am	Emissions observed at the enclosed combustor Video by Daniel Hoyt	
DSC00768	10:18 am	Data Output Screen, Condensate Storage Tank Levels (in inches) Photograph by Natalia Vazquez	
DSC00769	10:19 am	Data Output Screen, Produced Water Storage Tanks Levels (in inches) Photograph by Natalia Vazquez	
DSC00770	10:22 am	Sand traps Photograph by Natalia Vazquez	
DSC00771	10:22 am	GPUs Photograph by Natalia Vazquez	
DSC00772	10:35 am	Stabilizers, Out of Service Photograph by Natalia Vazquez	

DSC00773	10:36 am	Heater Treater	
		Photograph by Natalia Vazquez	
DSC00774	10:37 am	Wellheads	
		Photograph by Natalia Vazquez	
DSC00775	10:39 am	Sand traps	
		Photograph by Natalia Vazquez	
DSC00776	10:39 am	GPUs	
		Photograph by Natalia Vazquez	
DSC00777	10:41 am	NGL Storage Tank, Out of Service	
		Photograph by Natalia Vazquez	
DSC00778	10:42 am	Enclosed Combustor	
		Photograph by Natalia Vazquez	
DSC00779	10:43 am	Label of Condensate Storage Tank #5, WV /AST # 052-00000338, Leak from the	
		pressure relief valve (Enardo 950) was observed (Group of 5 Tanks next to the NGL	
		Tank)	
		Photograph by Notalia Vazquez	
DSC00780	10:54 am	Label of Condensate Storage Tank #3, WV AST # 052-00001029, Leak from thief hatch	
		was observed (Group of 5 Tanks next to the NGL Tank)	
		Photograph by Natalia Vazquez	
DSC00781	10:54 am	Label of Condensate Storage Tank #2, WV AST # 052-00000311, Leak from thief hatch	
	STATES TO M	was observed (Group of 5 Tanks next to the NGL Tank)	
		Photograph by Natalia Vazquez	
DSC00782	10:54 am	Label of Condensate Storage Tank #1, WV AST # 052-00000322, Leak from thief hatch	
		was observed (Group of 5 Tanks next to the NGL Tank)	
		Photograph by Natalia Vazquez	
MOV_0232	11:16 am	Emissions observed at the enclosed combustor (high sensitivity mode only)	
		Video by Daniel Hoyt	
DSC00783	11:17 am	Storage Tanks, 14 tanks in total, divided into 3 groups	85
22000.00		Photograph by Natalia Vazquez	
DSC00784	11:19 am	Five Storage Tanks, the group that is next to the NGL Storage Tank	
23000.01		Photograph by Natalia Vazquez	
MOV 0233	11:19 am	Leak from the pressure relief valve (Enardo 950) was observed at Condensate Storage	150 ppm
1.10 1 _0233		Tank #5, WV /AST # 052-00000338, (Group of 5 Tanks next to the NGL Tank)	

		Video by Daniel Hoyt	
MOV 0234	11:20 am	Leak from thief hatch was observed at Condensate Storage Tank #3, WV AST # 052-	25 ppm
-		00001029 (Group of 5 Tanks next to the NGL Tank)	(*)
		Video by Daniel Hoyt	
MOV	11:21 am	Leak from thief hatch was observed at Condensate Storage Tank #2, WV AST # 052-	40 ppm
_0235		00000311, (Group of 5 Tanks next to the NGL Tank)	
		Video by Daniel Hoyt	
MOV_0236	11:22 am	Leak from thief hatch was observed at Condensate Storage Tank #1, WV AST # 052-	180 ppm
		00000322, (Group of 5 Tanks next to the NGL Tank)	
		Video by Daniel Hoyt	
MOV_0237	11:24 am	Leak from thief hatch was observed at Condensate Storage Tank #4, WV AST # 052-	10 ppm
		00000350, (Group of 5 Tanks that is between the other two groups of tanks)	
		Video by Daniel Hoyt	
DSC00785	11:25 am	Label of Condensate Storage Tank #4, WV AST # 052-00000350, Leak from thief hatch	
		was observed (Group of 5 Tanks that is between the other two groups of tanks)	
		Photograph by Natalia Vazquez	
MOV_0238	11:25 am	Leak from thief hatch was observed Condensate Storage Tank #3, WV AST # 052-	170 ppm
		00000328 (Group of 5 Tanks that is between the other two groups of tanks)	
		Video by Daniel Hoyt	
DSC00786	11:26 am	Label of Condensate Storage Tank #3, WV AST # 052-00000328, Leak from thief hatch	
		was observed (Group of 5 Tanks that is between the other two groups of tanks)	
		Photograph by Natalia Vazquez	
DSC00787	11:26 am	Label of Produced Water Storage Tank #2, WV AST # 052-00001031, Leak from thief	
		hatch was observed (Group of 5 Tanks that is between the other two groups of tanks)	
		Photograph by Natalia Vazquez	l
MOV_0239	11:26 am	Leak from thief hatch was observed Condensate Storage Tank #2, WV AST # 052-	17 ppm
		00001031 (Group of 5 Tanks that is between the other two groups of tanks)	
		Video by Daniel Hoyt (EPA)	
MOV_0240	11:27 am	Leak from pressure relief valve was observed Condensate Storage Tank #1, WV AST #	
		052-00001027 (Group of 5 Tanks that is between the other two groups of tanks), odor	
		detected by Natalia Vazquez	
		Video by Daniel Hoyt	

MOV_0241	11:28 am	Leak from thief hatch was observed Condensate Storage Tank #1, WV AST # 052-	60 ppm
		00001027 (Group of 5 Tanks that is between the other two groups of tanks)	50,00°4.0
		Video by Daniel Hoyt	
DSC00788	11:29 am	Label of Produced Water Storage Tank #1, WV AST # 052-00001027, Leak from thief	{
		hatch was observed (Group of 5 Tanks that is between the other two groups of tanks)	
		Photograph by Natalia Vazquez	
MOV 0242	11:29 am	Leak from thief hatch was observed of Produced Water Storage Tank #3, WV AST # 052-	50 ppm
_		00000298, (Group of 4 Tanks that is closest to the site's gate)	
		Video by Daniel Hoyt	
MOV 0243	11:30 am	Label of Produced Water Storage Tank #2, WV AST # 052-00000345, Leak from thief	70 ppm
_		hatch was observed (Group of 4 Tanks that is closest to the site's gate)	
		Video by Daniel Hoyt	
DSC00789	11:31 am	Leak from thief hatch was observed of Produced Water Storage Tank #3, WV AST # 052-	
		00000298, (Group of 4 Tanks that is closest to the site's gate)	
		Photograph by Natalia Vazquez	
MOV_0244	11:31 am	Leak from thief hatch was observed of Produced Water Storage Tank #1, WV AST # 052-	12 ppm
		00000333, (Group of 4 Tanks that is closest to the site's gate)	
		Video by Daniel Hoyt	
DSC00790	11:32 am	Label of Produced Water Storage Tank #2, WV AST # 052-00000345, Leak from thief	
		hatch was observed (Group of 4 Tanks that is closest to the site's gate)	
		Photograph by Natalia Vazquez	
DSC00791	11:32 am	Label of Produced Water Storage Tank #1, WV AST # 052-00000333, Leak from thief	
		hatch was observed (Group of 4 Tanks that is closest to the site's gate)	
		Photograph by Natalia Vazquez	
		Facility: Hoyt 403	
File	Time	Description	PID reading
Number			
DSC00792	11:56 am	Sign at entrance of Hoyt 403 wellpad	
		Latitude: 39.5992N	
		Longitude:80.6539W	
		Address: 6887 Hoyt Ridge Rd.	
		Wileyville, WV 26581	
		Photograph by Daniel Hoyt	

MOV_0245	11:57	Video with cap on – Please disregard	
100.00		Video by Daniel Hoyt	
DSC00793	12:03 pm	Storage Tanks	
		Photograph by Natalia Vazquez	
DSC00794	12:03 pm	Enclosed Combustor	
		Photograph by Natalia Vazquez	
MOV_0246	12:03 pm	Leak observed at GPU 1H	
		Video by Daniel Hoyt	82
MOV_0247	12:04 pm	Leak observed at GPU 1H	5 ppm
<u></u>		Video by Daniel Hoyt	- PP
MOV_0248	12:07 pm	Leak observed at GPU 1H – diaphragm	8 ppm
		Video by Daniel Hoyt	o pp
DSC00795	12:14 pm	Knockout Water Tank, Out of Service	-
MOV_0249	12:17 pm	leak found in Thief Hatch,of Produced Water Storage Tank WV ATS # 052-00000347	
		(Tank #1 North)	
		Video by Daniel Hoyt	
DSC00796	12:20 pm	Label of Produced Water Storage Tank, WV ATS # 052-00000347, leak found in Thief	120 ppm
		Hatch, (Tank #1 North)	1
		Photograph by Natalia Vazquez	
DSC00797	12:23 pm	Gun Barrel Tank, WV AST # 052-00000327, stains on tank's surface	
		Photograph by Natalia Vazquez	
DSC00798	12:26 pm	Label of Tank WV AST # 052-00000309, stains on tank's surface	
	2	Photograph by Natalia Vazquez	
DSC00799	12:26 pm	Gun Barrel Tank, stains on tank's surface	
		Photograph by Natalia Vazquez	
		Facility: Hoyt 402	
File	Time	Description	PID reading
Number			
DSC00800	12:38 pm	Sign at entrance of Hoyt 402 wellpad	
		Latitude: 39.5986N	
		Longitude:80.6519W	
		Address: 6879 Hoyt Ridge Rd.	
		Wileyville, WV 26581	

		Photograph by Daniel Hoyt	
DSC00801	1:06 pm	Wellhead	
	1.5	Photograph by Natalia Vazquez	20
MOV_0250	1:09 pm	Leak observed at GPU 6H, an odor was detected by Ms. Vazquez	20 ppm
_	•	Video by Daniel Hoyt	
MOV_0251	1:16 pm	Leak observed from thief hatch Condensate Storage Tank, WV AST# 052-00000312, (the	
_	<u></u>	group of tanks near combustor)	
		Video by Daniel Hoyt	
DSC00802	1:17 pm	Storage Tanks	
	p massans J ames	Photograph by Natalia Vazquez	20
DSC00803	1:19 pm	Label of Condensate Storage Tank, WV AST# 052-00000312, leak observed from thief	20 ppm
モ が.: 単		hatch (the group of tanks near combustor)	
		Photograph by Natalia Vazquez	200
MOV 0252	1:21 pm	Leak observed from thief hatch of Condensate Storage Tank, WV AST# 052-00000320,	200 ppm
_		(the group of tanks near combustor)	
		Video by Daniel Hoyt	150
MOV_0253	1:23 pm	Leak observed from thief hatch of Produced Water Storage Tank, WV AST# 052-	150 ppm
-		00000332, (the group of tanks near combustor)	
		Video by Daniel Hoyt	4
DSC00804	1:24 pm	Label of Condensate Storage Tank, WV AST# 052-00000320, leak observed from thief	
	000 W000 R C. 1 100 P 100 W00 W00 W00	hatch (the group of tanks near combustor)	
		Photograph by Natalia Vazquez	90
MOV 0254	1:25 pm	Leak observed from thief hatch of Produced Water Storage Tank, WV AST# 052-	80 ppm
		00000312, (the group of tanks near GPUs)	
		Video by Daniel Hoyt	
DSC00805	1:26 pm	Label of Produced Water Storage Tank, WV AST# 052-00000332, leak observed from	
		thief hatch (the group of tanks near combustor)	
		Photograph by Natalia Vazquez	
DSC00806	1:27 pm	Label of Produced Water Storage Tank, WV AST# 052-00000312, leak observed from	
		thief hatch (the group of tanks near GPUs)	
		Photograph by Natalia Vazquez	150
MOV 0255	1:30 pm	Leak observed from thief hatch of Condensate Storage Tank, WV AST# 052-00000339,	150 ppm
		(the group of tanks near GPUs), odor detected by Mr. Hoyt	(intermitten

		Video by Daniel Hoyt	
DSC00807	1:31 pm	Label of Condensate Storage Tank, WV AST# 052-00000339, leak observed from thief	
		hatch (the group of tanks near GPUs)	
		Photograph by Natalia Vazquez	
MOV_0257	1:34 pm	Leak observed from thief hatch of Storage Tank, WV AST# 052-00000314, (the group of tanks near GPUs), odor detected by Mr. Hoyt and Ms. Vazquez Video by Daniel Hoyt	140 ppm
MOV_0258	1:35 pm	Leak observed from thief hatch of Produced Water Storage Tank, WV AST # 052-00000324, (the group of tanks near GPUs), odor detected by Mr. Hoyt and Ms. Vazquez Video by Daniel Hoyt	158 ppm
DSC00808	1:37 pm	Label of Produced Water Storage Tank, WV AST # 052-00000314, leak observed from thief hatch (the group of tanks near GPUs) Photograph by Natalia Vazquez	
MOV_0259	1:37 pm	Leak observed from the ground, tanks WV AST # 052-00000314 and WV AST # 052-00000324 Video by Daniel Hoyt	148
DSC00809	1:38 pm	Label of Produced Water Storage Tank, WV AST# 052-00000324, leak observed from thief hatch (the group of tanks near GPUs) Photograph by Natalia Vazquez	154 ppm
DSC00810	1:39 pm	Stains in Produced Water Storage Tank Photograph by Natalia Vazquez	
		Facility: Hoyt 401	
File Number	Time	Description	PID reading
DSC00811	1:59 pm	Sign at entrance of Hoyt 401 wellpad Latitude: 39.5975N Longitude:80.6522W Address: 5917 Hoyt Ridge Rd. Wileyville WV 26581 Photograph by Daniel Hoyt	
DSC00812	2:13 pm	Sky reflection in Data Output Screen Photograph by Natalia Vazquez	
DSC00813	2:20 pm	Stains in Gun Barrel Tank, WV AST # 052-00000299	

		Photograph by Natalia Vazquez	
DSC00814	2:22 pm	Stains in Gun Barrel Tank, WV AST # 052-00000299	-
	•	Photograph by Natalia Vazquez	
		Facility: Hoyt 404	NID 1'
File Number	Time	Description	PID reading
DSC00815	2:31 pm	Sign at entrance of Hoyt 404 wellpad	
		Latitude: 39.6111N	
		Longitude:80.6378W	
		Address: 5764 Hoyt Ridge Rd.	
		Wileyville, WV 26581	
		Photograph by Daniel Hoyt	
DSC00816	2:32 pm	Sign at entrance of Hoyt 404 wellpad	
		Photograph by Natalia Vazquez	
DSC00817	2:35 pm	Wellheads Gun Barrel Tanks, and Storage Tanks	
	The second secon	Photograph by Natalia Vazquez	
DSC00818	2:40 pm	Sky reflection in Data Output Screen	
		Photograph by Natalia Vazquez	
	•	Facility WJ Criswell 405	PID reading
File	Time	Description	PID reading
Number			
DSC00819	2:57 pm	Sign at entrance of WJ Criswell 405	
	1	Latitude: 39.6086 N	
		Longitude:80.6181 W	
		Address: 4515 Hoyt Ridge Rd.	
		Wileyville, WV 26581	
		Photograph by Daniel Hoyt	
DSC00820	2:57 pm	Sign at entrance of WJ Criswell 405	
		Photograph by Daniel Hoyt	
DSC00821	3:04 pm	Data Output Screen, Gas Meter, MarkWest Gas Sales Meter	
	5.70	Photograph by Natalia Vazquez	
DSC00822	3:05 pm	Data Output Screen, Condensate (Oil) Storage Tanks levels (in inches)	
		Photograph by Natalia Vazquez	

DSC00823	3:06 pm	Data Output Screen, Produced Water Storage Tanks levels (in inches)	
		Photograph by Natalia Vazquez	
DSC00824	3:06 pm	Data Output Screen, Produced Water Storage Tanks levels (in inches)	
		Photograph by Natalia Vazquez	
MOV_0260	3:07 pm	Leak observed from thief hatch of Produced Water Storage, WV AST # 052 – 00001147,	50 ppm
		Video by Daniel Hoyt	э о ррии
MOV 0261	3:10 pm	Leak observed from thief hatch of Produced Water Storage, WV AST # 052 – 00001144	100 ppm
	•	Video by Daniel Hoyt	тоо ррш
DSC00825	3:15 pm	Label of Produced Water Storage, WV AST # 052 – 00001147, leak observed from thief	50 ppm
		hatch	э о ррш
		Photograph by Natalia Vazquez	
DSC00826	3:15 pm	Label of Produced Water Storage, WV AST # 052 – 00001144, leak observed from thief	100 ppm
		hatch	l oo pp
		Photograph by Natalia Vazquez	
		Facility: Mary Miller GRT WZ	
File	Time	Description	PID reading
Number			l i i i i i i i i i i i i i i i i i i i
DSC00827	3:23 pm	Sign at entrance of Mary Miller GRT WZ wellpad	
		Latitude: 39.6156 N	
		Longitude:80.6144 W	
		Address: 4435 Hoyt Ridge Rd	
		Wileyville WV 26581	
	<u></u>	Photograph by Daniel Hoyt	

et.			

Vazquez, Natalia

From: Hoyt, Daniel

Sent: Thursday, September 28, 2017 3:37 PM

To: Jon Hickman

Cc: Bob Adams; Vazquez, Natalia

Subject: Ascent Resources Well Pads Visited by EPA on September 18, 2017

Hello Jon Hickman,

Thank you for accompanying me and Natalia Vazquez at the Long 408/409, Hoyt 403, Hoyt 402, Hoyt 401, Hoyt 404, WJ Criswell 405, and Mary Miller GRT well pads, on September 18, 2017. During our exit briefing on September 21, 2017, we asked for some documents, and/or information. As a reminder, I said I would send you a list of the items that we asked for. Please provide the following documents and/or information by October 12, 2017:

- 1. Copies of permit application response(s) and approval from the West Virginia Department of Environmental Protection (WVDEP) for current authorization of the air emissions sources at the WJ Criswell 405 well pad;
- 2. Copies of construction and/or operating permit applications that were submitted most recently to WVDEP that provide representations regarding the operating conditions for the air emissions sources at the Long 408/409, Hoyt 403, Hoyt 401, Hoyt 404, WJ Criswell 405, and Mary Miller GRT well pads;
- 3. The make and model, expected destruction efficiency, and maximum and minimum design gas flow rates for each control device (flare of vapor combustor) at the Long 408/409, Hoyt 403, Hoyt 402, Hoyt 401, Hoyt 404, and Mary Miller GRT well pads;
- 4. Copies of existing closed vent system and control device design analyses, if any, that evaluate the sizing of the closed vent systems and control devices at the Long 408/409, Hoyt 403, Hoyt 402, Hoyt 401, Hoyt 404, and Mary Miller GRT well pads, based on the maximum expected liquid and gas flow rates. If available, please include the date of the analysis, the maximum expected liquid and gas flow rates, sample results of liquids and gases used for the analysis, and example calculations/descriptions of methodologies used to estimate flash emissions and maximum vent system flow rates;
- 5. Copies of documentation, if any, indicating pneumatic controllers at the Long 408/409, Hoyt 403, Hoyt 402, Hoyt 401, Hoyt 404, WJ Criswell 405, and Mary Miller GRT well pads have bleed rates less than or equal to 6 standard cubic feet per hour;
- 6. Copies of existing SOPs if any, for inspections and preventative maintenance of critical equipment necessary for preventing/minimizing releases and leaks (such as emergency shutoff devices, thief hatches and pressure relief devices), at the Long 408/409, Hoyt 403, Hoyt 402, Hoyt 401, Hoyt 404, WJ Criswell 405, and Mary Miller GRT well pads. If available, please include example records of recent inspection and preventative maintenance activities at the identified location;
- 7. Copies of existing SOPs for leak detection and repair activities, if any, at the Long 408/409, Hoyt 403, Hoyt 402, Hoyt 401, Hoyt 404, WJ Criswell 405, and Mary Miller GRT well pads, including use of 40 CFR part 60, Appendix A-7, Method 21, optical gas imaging instruments such as an infrared cameras, and/or audio, visual or olfactory methods for leak detection. If available, please include example records of recent leak detection and repair activities at the identified locations;
- 8. A list of the American Petroleum Institute (API) well numbers for each well at the Long 408/409, Hoyt 403, Hoyt 402, Hoyt 401, Hoyt 404, WJ Criswell 405, and Mary Miller GRT well pads, and indicate the well pad name and the date of well completion for each listed well; and
- 9. Confirm that the Hoyt 404 well pad is it also known as the John Rush 404 well pad. If the Hoyt 404 and John Rush 404 are not the same well pad, provide copies of permit application response(s) and approval from WVDEP for current authorization of the air emissions sources at the Hoyt 404 well pad, and the following information for the John Rush 404 well pad:



- a. Copies of construction and/or operating permit applications that were submitted most recently to WVDEP that provide representations regarding the operating conditions for the air emissions sources;
- Copies of existing closed vent system design analyses, if any, that evaluate the sizing of the closed vent system(s) and control device(s) as described in item 3 above;
- c. Copies of existing SOPs if any, for inspections and preventative maintenance of critical equipment necessary for preventing/minimizing releases and leaks (such as emergency shutoff devices, thief hatches and pressure relief devices), and example records of recent inspection and preventative maintenance activities, if any; and
- d. Copies of existing SOPs for leak detection and repair activities, if any, and example records, if any, as described in item 5 above.

If any of the above requested documents or information are not available, please indicate as such in the response, and include the reason the requested documents or information are not available. If you will be providing your response by mail please send the response to:

Natalia I Vazquez Rivera
Office of Air Enforcement and Compliance Assistance
U.S. Environmental Protection Agency
1650 Arch Street (3AP20)
Philadelphia, PA 19103-2029

Regards,

Dan Hoyt

Daniel Hoyt, Environmental Engineer
US Environmental Protection Agency
Office of Enforcement and Compliance Assurance
Office of Civil Enforcement - Air Enforcement Division
(202) 564-7898
1200 Pennsylvania Ave, NW
WJC-S, MC 2242A
Washington, DC 20460 (mail) or 20004 (courier)